Vehicle Systems Report

12/09/2022 11:26 AM CST Repair order 76254 Technician ID RG216 Customer Name Hunter

Year: 2020 Make: Ford Model: Escape

Submodel: Titanium Hybrid

Engine: 2.5

VIN: 1FMCU0DZ4LUA10548

Odometer 12378



Hunter Engineering 11250 Hunter Dr. Bridgeton MO 63044

Scantool: Hunter Software Version 5.4.1.6 Serial #: 00DVMN5021021558HU

Diagnostics software featuring officially licensed OEM data from ETI

| Diagnostic Health Report | | | |
|---------------------------|---|--|--------------------------------------|
| | | Pre-Scan 12/09/2022 10:59 AM CST | Post-Scan 12/09/2022 11:25 AM CST |
| Modules Scanned: | | 36 | 36 |
| Diagnostic Trouble Codes: | | 70 | 5 |
| System | | | |
| ABS / TRACTION CONTROL | | 9 | OK |
| P05D3-86 | Driver Mode Select Switch "A" Range/Performance - Invalid/Incompatible Configuration | CURRENT PENDING CODES FAIL SINCE CLEAR | ОК |
| U0100-00 | Lost Communication With ECM/Powertrain Control Module "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U0101-00 | Lost Communication With TCM - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U0131-00 | Lost Communication With Power Steering Control Module "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| U0146-00 | Lost Communication With Serial Data Gateway "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U0151-00 | Lost Communication With Restraints Control Module - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U0159-00 | Lost Communication With Parking Assist Control Module "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| U0164-00 | Lost Communication With HVAC Control Module - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U0420-00 | Invalid Data Received from Power Steering Control Module "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |

| ACCESSORY PROTOCOL INTER | FACE | 2 | ОК |
|---------------------------|--|---------------------------|-----------------|
| U1A00-87 | Private Communication Network - Invalid/Incompatible Software Component | HISTORY | ОК |
| U3003-16 | Battery Voltage | HISTORY | ОК |
| AIR CONDITIONING CONTROL | | 2 | ОК |
| P0562-00 | System Voltage Low - No Sub Type Information | HISTORY | ОК |
| U0111-00 | Lost Communication With Battery Energy Control Module (A) - No Sub Type Information | HISTORY | ОК |
| AUDIO CONTROL MODULE | | 1 | 1 |
| U0100-00 | Lost Communication With ECM/Powertrain Control Module "A" - No Sub Type Information | CURRENT HISTORY | CURRENT HISTORY |
| BATTERY ENERGY CONTROL M | IODULE | 5 | ОК |
| POAOC-00 | High Voltage System Interlock Circuit "A" Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| P1A0F-68 | Hybrid Powertrain Control Module - Vehicle Disabled - Data Memory Failure | HISTORY FAIL SINCE CLEAR | ОК |
| U3003-16 | Battery Voltage | HISTORY FAIL SINCE CLEAR | ОК |
| U3012-00 | Control Module Improper Wake-Up Performance - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U3517-00 | High Voltage System Interlock Circuit "C" Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| BATTERY ENERGY CONTROL M | IODULE B | 2 | ОК |
| B1142-62 | Ignition Status 1 | HISTORY | ОК |
| B13BF-14 | Run/Start Input | HISTORY | ОК |
| BODY CONTROL MODULE | | 1 | ОК |
| U0258-87 | Lost Communication With Radio Transceiver - Invalid/Incompatible Software Component | HISTORY | ОК |
| DIGITAL SIGNAL PROCESSING | | 1 | ОК |
| U3003-16 | Battery Voltage | HISTORY | ОК |
| DRIVER DOOR MODULE | | 4 | 1 |
| B118E-01 | Left Front Window - General Electrical Failure | HISTORY | |

| B1190-01 | Left Rear Window - General Electrical Failure | HISTORY | |
|-------------------------|---|--|-----------------|
| B12DD-54 | Rear Window Motion/Position Sensor - Signal Frequency Too Low | CURRENT HISTORY | CURRENT HISTORY |
| U3003-16 | Battery Voltage | HISTORY | |
| GEAR SHIFT MODULE | | 3 | ОК |
| P0562-00 | System Voltage Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| | Invalid Internal Control | | |
| U1011-00 | Module Monitoring Data Received From ECM/PCM - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| U101F-00 | Invalid Internal Control Module Monitoring Data Received From Transmission Range Control Module - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| HEAT VENT A/C | | 2 | ОК |
| B10B8-63 | Push Buttons | HISTORY | ОК |
| U3003-16 | Battery Voltage | HISTORY | OK |
| IMAGE PROCESSING MODULE | A ADAS | 4 | OK |
| C1001-54 | Vision System Camera - Signal Frequency Too Low | CURRENT PENDING CODES HISTORY FAIL SINCE CLEAR MIL CODES | OK |
| C1001-78 | Vision System Camera | CURRENT PENDING CODES HISTORY FAIL SINCE CLEAR MIL CODES | OK |
| U0418-86 | Invalid Data Received From Brake System Control Module "A" - Invalid/Incompatible Configuration | HISTORY FAIL SINCE CLEAR | OK |
| U3003-16 | Battery Voltage | HISTORY FAIL SINCE CLEAR | OK |
| INSTRUMENT CLUSTER | | 2 | 1 |
| U0293-82 | Lost Communication With Hybrid/EV Powertrain Control Module - Not Activated | CURRENT | CURRENT |
| U3003-16 | Battery Voltage | HISTORY | |
| OCCUPANT CLASSIFICATION | | 1 | ОК |
| | | | |

| U0100-00 | Lost Communication With ECM/Powertrain Control Module "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
|-----------------------------|--|---------------------------|---------|
| PASSENGER FRONT DOOR MODULE | | 5 | 2 |
| B118F-01 | Right Front Window - General Electrical Failure | HISTORY | |
| B1191-01 | Right Rear Window - General Electrical Failure | HISTORY | |
| B12DC-54 | Front Window Motion/Position Sensor - Signal Frequency Too Low | CURRENT HISTORY | CURRENT |
| B12DD-54 | Rear Window Motion/Position Sensor - Signal Frequency Too Low | CURRENT | CURRENT |
| U3003-16 | Battery Voltage | HISTORY | |
| PEDESTRIAN ALERT CONTROL | ADAS | 1 | OK |
| U3003-16 | Battery Voltage | HISTORY | ОК |
| POWER STEERING CONTROL | | 1 | ОК |
| U3003-16 | Battery Voltage | HISTORY | ОК |
| POWERTRAIN CONTROL MOD | ULE | 4 | ОК |
| P0562-00 | System Voltage Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| P05A7-00 | Active Grille Air Shutter "A" Supply Voltage Circuit Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U0284-00 | Lost Communication With Active Grille Air Shutter Module "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| U1010-00 | Invalid Internal Control Module Monitoring Data Received From Hybrid Powertrain Control Module - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| REAR GATE/TRUNK MODULE | | 2 | ОК |
| U3003-16 | Battery Voltage | HISTORY | OK |
| U3003-17 | Battery Voltage - Circuit Short To Ground | HISTORY | OK |
| RESTRAINT CONTROL MODUL | E | 4 | ОК |
| B00DF-4A | Passenger Restraints Disable Switch - Invalid/Incompatible Configuration | HISTORY FAIL SINCE CLEAR | ОК |
| U0112-00 | Lost Communication With Battery Energy Control Module "B" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| | Invalid Data Received From | HISTORY | |

| U0413-92 | Battery Energy Control Module "B" | FAIL SINCE CLEAR | ОК |
|--------------------------------|---|---------------------------|----|
| U3003-16 | Battery Voltage | HISTORY FAIL SINCE CLEAR | ОК |
| SECONDARY OBD CONTROL MODULE C | | 11 | OK |
| C0564-00 | ABS Control Module System Voltage Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| C056B-00 | Brake Pressure Sensor "A" Intermittent/Erratic - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| C0596-00 | Brake Booster Motor "A" Current Sensor Circuit Range/Performance - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| P0562-00 | System Voltage Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| P0613-86 | TCM Processor - Invalid/Incompatible Configuration | HISTORY FAIL SINCE CLEAR | OK |
| P0887-00 | TCM Power Relay Control Circuit High - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| P0A7D-00 | Hybrid/EV Battery Pack State Of Charge Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | ОК |
| P0D6D-00 | A/C Compressor "A" Motor Voltage "A" Low - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| P1A07-00 | Inverter High Voltage Performance - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| P1A10-00 | Hybrid Powertrain Control Module - Battery Disabled - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| U1028-00 | ABS Control Module Received Invalid Data From ECM/PCM "A" - No Sub Type Information | HISTORY FAIL SINCE CLEAR | OK |
| STEERING COLUMN CONTROL MODULE | | 2 | ОК |
| U3003-A2 | Battery Voltage - Circuit Short To Ground | HISTORY FAIL SINCE CLEAR | OK |
| U3003-A3 | Battery Voltage - Circuit Short To Ground | HISTORY FAIL SINCE CLEAR | OK |
| TELEMATIC CONTROL UNIT M | ODULE | 1 | ОК |
| U3003-16 | Battery Voltage | HISTORY | ОК |
| CRUISE CONTROL MODULE AD | DAS | ОК | ОК |
| DC TO DC CONVERTER CONTROL | | ОК | ОК |
| | | _ | |

| DRIVER FRONT SEAT MODULE | ОК | ОК |
|--------------------------------------|-----------|-----------|
| GATEWAY MODULE A | ОК | ОК |
| SIDE OBSTACLE DETECTION - LEFT ADAS | ОК | ОК |
| SIDE OBSTACLE DETECTION - RIGHT ADAS | ОК | ОК |
| TPM RADIO TRANSCEIVER MODULE | ОК | ОК |
| ALL WHEEL DRIVE MODULE | NOT FOUND | NOT FOUND |
| HEAD UP DISPLAY | NOT FOUND | NOT FOUND |
| IMAGE PROCESSING MODULE B ADAS | NOT FOUND | NOTFOUND |
| PARKING AID MODULE ADAS | NOT FOUND | NOTFOUND |
| TRAILER MODULE | NOT FOUND | NOT FOUND |
| WIRELESS ACCESSORY CHARGING | NOT FOUND | NOT FOUND |

Pre-Scan Photos







Post-Scan Photos







no fault verification road test

ADAS Calibration

 $Cameras\ are\ used\ to\ monitor\ vehicle\ surroundings\ for\ Advanced\ Driver\ Assistance\ Systems\ (ADAS).\ These\ systems\ assist\ the\ driver\ using\ warnings,\ braking,\ or\ steering\ actions\ to\ maintain\ lane\ position\ or\ to\ mitigate\ collision\ risk.\ Calibration\ helps\ to\ ensure\ the\ system\ performs\ properly.$

Front Facing Camera Front Camera Calibration

COMPLETE


12/09/2022 11:17 AM CST

Photos









| Signature of Approval | |
|-----------------------|------|
| Customer Signature | Date |